

PB6074BL/PB6074RW – Geriatric Recliners

Assembly Notice

During assembly, the back frame may be difficult to engage with the lower frame.

Solution:

It is recommended that 2 persons assemble the chair. To assemble the back more easily, position it in the fully reclined setting and flip it over so that the bolts are facing up. Once the back frame (fig. 1) has slid all the way into the lower frame, the two back panel bolt holes (fig 2) will align with the two lower frame holes (fig 2 & 3).

